Issues

#	Project	Tracker	Status	Priority	Subject	Updated
2587	CHIRP	Bug	New	Normal	Cannot Import CSV into a UV-5R image file, error thrown 'no attribute power in struct'	05/14/2015 08:10 pm
2585	CHIRP	Bug	New	High	'Power' column not imported or exported [UV-5R]	05/14/2015 12:03 pm
2583	CHIRP	New Model	New	Normal	Pofung BF-F9+TP	05/14/2015 08:29 am
2581	CHIRP	Bug	Feedback	Normal	Call signs do not load to Kenwood TM-281A	05/12/2015 03:53 pm
2579	CHIRP	Bug	Feedback	Normal	Have new BF-F8HP and the the "incorrect model selected" Message.	05/13/2015 07:22 pm
2577	CHIRP	New Model	New	High	HYT TC 2110	05/11/2015 09:07 pm
2575	CHIRP	Bug	New	Normal	Kenwood TH-K2 Channel Numbers	05/08/2015 07:39 am
2573	CHIRP	New Model	Blocked	Normal	Tera TR-590	05/07/2015 11:05 am
2571	CHIRP	Feature	New	Normal	Can I use another tone code besides the presets that are given in the list?	05/06/2015 05:56 pm
2565	CHIRP	New Model	New	Normal	AnyTone AT-398UV	05/05/2015 12:51 am
2563	CHIRP	Feature	New	Normal	[TERMN-8R] Please support adding memories to banks	05/03/2015 09:49 am
2561	CHIRP	Bug	Feedback	Normal	ft60 / prolific serial cable - will read from radio but won't write	05/03/2015 02:46 pm
2559	CHIRP	Feature	Resolved	Normal	[UV-B5] Expand Odd-Split Range and Add Cross-Band Support	05/01/2015 03:41 am
2555	CHIRP	New Model	New	Normal	AnyTone AT-3208	04/30/2015 09:54 am
2553	CHIRP	Bug	Feedback	Normal	bf-f8 won't receive	04/30/2015 04:54 pm
2551	CHIRP	Bug	In Progress	Normal	Baofeng BF-F8HP "Incorrect model selected"	04/30/2015 06:17 pm
2549	CHIRP	Bug	Resolved	High	Duplex and Offset fields not populated on Read From Radio	04/28/2015 03:29 pm
2547	CHIRP	Bug	Feedback	Normal	Baofeng UV-5R (N5R-2407 BFB297N)	05/06/2015 03:41 am
2545	CHIRP	Bug	New	High	[ft-7900] banks not working	04/28/2015 12:14 am
2543	CHIRP	Bug	Feedback	Immediate	Baofeng GT-3TP	04/28/2015 03:32 am
2541	CHIRP	Bug	New	Normal	YAESU FT-2900E -> Failed checksum on read	04/25/2015 10:37 pm
2537	CHIRP	Bug	New	Normal	Mixed firmware	04/25/2015 10:11 am
2535	CHIRP	Bug	New	Low	FT-60 UI Typos	04/23/2015 08:03 pm
2533	CHIRP	Bug	New	Normal	No RX no TX on Baofeng UV-5R (N5R-219BFB297)	04/27/2015 11:47 am
2531	CHIRP	New Model	New	Low	yaesu ft991	05/15/2015 04:06 am
2527	CHIRP	New Model	New	Normal	Vitai VT-UV2	04/17/2015 10:00 am
2525	CHIRP	New Model	Blocked	Normal	Connect Systems [CSI] CS-7000 HT, analog, DMR, D-Star	05/06/2015 06:21 pm
2523	CHIRP	Bug	New	Normal	simplex channel entry	04/14/2015 08:02 pm
2521	CHIRP	New Model	Feedback	Normal	Baofeng BF-UV9R+HP	04/25/2015 03:57 pm
2519	CHIRP	Bug	In Progress	Normal	[TERMN-8R] Signaling being randomly set	05/03/2015 06:05 pm
2517	CHIRP	Feature	New	Normal	[uv-5r] Rework Firmware Version Support	04/10/2015 06:52 pm
2515	CHIRP	Bug	New	Normal	bitwise.py:393:_get_value:TypeError: ord() expected a character, but string of length 0 found	04/23/2015 05:52 am

2513	CHIRP	New Model	New	Normal	Yaesu FT-1500M	04/17/2015 10:21 pm
2511	CHIRP	New Model	Feedback	Normal	Baofeng BF-F9 V2 Programing issue	04/12/2015 05:58 am
2509	CHIRP	Bug	In Progress	Normal	Settings tab for Yaesu FT-1DR does not display	05/14/2015 08:19 pm
2505	CHIRP	Bug	New	Normal	FT-2900 split tones entered via CHIRP UI can cause lock-ups	04/06/2015 09:56 pm
2503	CHIRP	Bug	New	Normal	Baofeng uv85c	04/06/2015 06:06 pm
2501	CHIRP	Bug	New	Normal	Yaesu FT-1900r can not read header	04/07/2015 07:30 am
2499	CHIRP	Bug	Resolved	Normal	unable to load module:cannot import name RadioSettings	04/12/2015 03:08 pm
2497	CHIRP	Bug	New	Normal	unable to load module:cannot import name	04/04/2015 01:32 pm
2495	CHIRP	New Model	New	Normal	Infinity P-1000 VHF	04/04/2015 09:12 am
2493	CHIRP	New Model	New	Normal	Alinco DJ-296	04/03/2015 12:49 am
2491	CHIRP	New Model	New	Normal	Alinco DR-605 support	04/02/2015 02:09 pm
2489	CHIRP	New Model	New	Normal	TYT TH-F8	04/02/2015 04:00 am
2483	CHIRP	Bug	Feedback	Normal	Cash Donation	04/02/2015 04:37 pm
2479	CHIRP	Bug	Feedback	Normal	Unable to Disable Transmit to Create Receive-only Channels	04/16/2015 10:42 am
2477	CHIRP	Bug	Feedback	Normal	Error when reading Yaesu FT-2800M	04/03/2015 05:21 pm
2475	CHIRP	New Model	Feedback	Normal	UV-5R error Incorrect model selected	04/25/2015 01:20 am
2467	CHIRP	New Model	New	High	Icom F4GS and F25	03/29/2015 11:10 am
2465	CHIRP	Bug	Feedback	High	OSX Hard Lockup When Radio Disconnected	03/30/2015 01:50 pm
2463	CHIRP	Bug	Feedback	Low	Channel names are truncated in the display	03/31/2015 05:41 am
2461	CHIRP	Bug	Resolved	Normal	An Error Has Occured, New user	03/27/2015 03:07 pm
2459	CHIRP	Bug	Feedback	Normal	Baofeng UV82 FW B82S27 refuses to send block 0x0000	04/05/2015 12:56 pm
2457	CHIRP	Bug	Feedback	Normal	Comm errors with BF-F8HP radio using Windows 7	04/12/2015 10:23 pm
2455	CHIRP	Bug	New	Normal	TH-D72a clone image: 2m channels don't work, radio does not transmit	03/25/2015 05:12 pm
2453	CHIRP	Bug	New	Normal	Bug Report & Questions/Comments	03/24/2015 10:20 am
2451	CHIRP	Bug	Feedback	Normal	Intek KT-980HP radio download error	03/25/2015 12:53 pm
2449	CHIRP	Bug	New	Normal	CHIRP won't Open on Windows 7 32 bit	03/23/2015 02:38 pm
2447	CHIRP	New Model	Feedback	Normal	baofeng bf-f8hp	03/25/2015 06:29 am
2445	CHIRP	Bug	New	Normal	FT-2900 doesn't always download cross tones that were entered via radio's UI	03/19/2015 09:00 pm
2443	CHIRP	New Model	New	Normal	uv-9r+hp	03/19/2015 09:55 am
2441	CHIRP	Bug	New	Normal	VX8DR	03/18/2015 07:40 pm
2437	CHIRP	New Model	In Progress	Normal	Anytone TERMN-8R	04/07/2015 04:53 am
2435	CHIRP	New Model	New	High	Wouxun KG-UV899	03/16/2015 10:14 pm
2433	CHIRP	Feature	New	Normal	FT-2900 should support cross tones	03/16/2015 07:32 pm
2431	CHIRP	Bug	Resolved	Normal	Comm port not shown	03/18/2015 06:12 pm
2429	CHIRP	Feature	New	Normal	Import State agencies through Radio Reference	03/15/2015 02:28 pm

2425	CHIRP	Feature	New	Normal	Add custom mic keys to settings	03/15/2015 08:36 am
2423	CHIRP	Bug	New	Normal	FT-2900 does not support odd splits.	03/14/2015 04:49 pm
2421	CHIRP	Bug	New	High	Can download but not upload to Gt-3 mark 3	03/25/2015 08:50 am
2419	CHIRP	New Model	New	Normal	Nanfone NF-6600	03/15/2015 11:33 am
2417	CHIRP	Bug	New	Normal	Name set in chirp not set in a radio	03/13/2015 02:18 pm
2415	CHIRP	Bug	New	Normal	Code downloaded incorrectly	03/13/2015 02:36 pm
2413	CHIRP	Bug	New	Normal	px-2r download fail	03/13/2015 01:51 pm
2409	CHIRP	Bug	New	Normal	Icom IC-2100H says "Unexpected response from radio"	03/12/2015 07:27 pm
2407	CHIRP	Bug	New	Normal	FT-50R	03/12/2015 10:25 am
2405	CHIRP	Bug	New	Normal	Chirp does not save/load subaudible tone frequencies properly	03/11/2015 07:58 am
2403	CHIRP	New Model	New	Urgent	kenwood TK-3302-1	03/09/2015 08:10 pm
2399	CHIRP	New Model	New	Normal	FT-7100 support	03/08/2015 04:31 pm
2397	CHIRP	Bug	New	Normal	file	03/08/2015 10:26 am
2395	CHIRP	New Model	New	Normal	icom IC-V8	03/07/2015 06:27 pm
2391	CHIRP	New Model	Feedback	Normal	support for Baofeng BF-F9 V2+	03/06/2015 05:02 pm
2387	CHIRP	Bug	New	Normal	Baofeng BF-F8HP Cant edit file after uploading from radio	03/04/2015 12:17 pm
2385	CHIRP	Bug	New	High	FT-2900 error message when adding new channel data through UI	03/04/2015 11:15 am
2381	CHIRP	Bug	New	Normal	FT-2900 should support banks	03/02/2015 03:49 pm
2379	CHIRP	New Model	New	Normal	Yeasu FT-2400	03/01/2015 09:39 pm
2377	CHIRP	Bug	In Progress	Normal	Wouxun UV8D V1.01 cannot see "Settings" tab in Chirp	03/06/2015 03:25 pm
2373	CHIRP	New Model	New	Normal	FTM-400D	02/28/2015 08:08 pm
2371	CHIRP	New Model	New	Normal	support VX-1R	02/27/2015 08:36 am
2369	CHIRP	Feature	In Progress	Normal	Exploring possible performance gains	02/26/2015 12:35 am
2363	CHIRP	Bug	New	Normal	chirp will not start of PC - windows 7	02/25/2015 03:40 pm
2361	CHIRP	Bug	New	Normal	Allow copying between radios where some settings are not supported	02/25/2015 12:51 pm
2355	CHIRP	Feature	Resolved	Normal	make codebase compliant with pep8	03/07/2015 10:38 pm
2353	CHIRP	New Model	New	Normal	Icom V80E	02/24/2015 05:17 am
2351	CHIRP	Feature	In Progress	Normal	move drivers and UI into new directories	03/01/2015 04:25 pm
2349	CHIRP	Feature	New	Normal	add option parsing to chirpw	02/24/2015 03:00 am
2347	CHIRP	Feature	In Progress	Normal	Add support for standard logging module	03/06/2015 07:00 am
2345	CHIRP	New Model	New	Normal	I have wanted to ask this for a while	02/23/2015 04:46 pm
2343	CHIRP	Feature	In Progress	Normal	chirpc: cleanup and modernize CLI	03/01/2015 04:26 pm
2341	CHIRP	Bug	Feedback	Normal	DTCS code	02/22/2015 03:09 pm
2339	CHIRP	Bug	Resolved	Normal	CHIRP daily-20150218 not connecting to UV5R 297, 307, 311	02/25/2015 02:30 am
2337	CHIRP	New Model	New	Normal	TYT DM-UVF10	02/20/2015 07:55 am

2335	CHIRP	Bug	Blocked	Normal	FT1D in daily builds	02/24/2015 02:14 am
2333	CHIRP	Bug	New	Normal	got a nv-5 that will not accept CHIRP	02/19/2015 05:01 pm
2331	CHIRP	Bug	New	Normal	TYT TH-9800 won't import split tone frequencies.	02/18/2015 07:45 pm
2329	CHIRP	Bug	New	Normal	Wouxon KG-UV8D Display Message Won't Upload to Radio	02/17/2015 04:33 pm
2327	CHIRP	Bug	New	Normal	Kenwood TM-281A Offset Changes Following Chirp	02/17/2015 04:23 pm
2323	CHIRP	Bug	New	Normal	Marine Frequencies	02/26/2015 01:03 pm
2319	CHIRP	Bug	Resolved	Normal	Baofeng BF-F8HP Unsupported firmware version: `N5R3403F8HP-1'	02/17/2015 04:06 pm
2317	CHIRP	Bug	In Progress	High	baofeng uv5R	04/09/2015 05:54 pm
2315	CHIRP	Bug	Feedback	Normal	Baofeng UV-5R - can't save to set frequencies	02/14/2015 05:52 pm
2313	CHIRP	Bug	Resolved	Normal	UV-5R+ no TX or RX	02/22/2015 03:05 pm
2311	CHIRP	New Model	New	Normal	Quansheng TG-UV2	03/06/2015 08:21 am
2305	CHIRP	New Model	New	Normal	TYT DM-UVF10	02/20/2015 07:51 am
2303	CHIRP	Bug	New	Normal	Problem programming Yaesu FT-2800M. Two different cables work with software from another vendor	02/10/2015 07:58 am
2301	CHIRP	Bug	New	High	OS X Freezes between walkie swaps	02/07/2015 05:21 pm
2297	CHIRP	Feature	New	Normal	chirpw launch script for Windows	02/07/2015 11:43 am
2295	CHIRP	New Model	New	High	No estaria mal...	02/07/2015 11:47 am
2293	CHIRP	New Model	New	Normal	UV-B5 with new firmware (27 menu entries) currently not supported	03/05/2015 02:08 pm
2291	CHIRP	Feature	New	Normal	"off" duplex for H-777	02/06/2015 04:09 pm
2289	CHIRP	Bug	Feedback	Normal	Windows 8.1	02/07/2015 11:54 am
2287	CHIRP	Feature	New	Normal	Wouxun KG-UV8D	02/04/2015 03:58 pm
2283	CHIRP	Bug	New	Normal	Raw memory indexes on special chans are invalid	02/01/2015 11:21 pm
2281	CHIRP	Bug	New	Normal	Error setting memory: Unable to calculate the required tuning step for 165.678750	02/03/2015 12:36 pm
2277	CHIRP	Bug	New	Normal	download from ID-880H results in "unexpected response from radio"	01/31/2015 06:14 pm
2271	CHIRP	Bug	New	Normal	Unable to program F8Hp with chirp	01/30/2015 06:54 pm
2269	CHIRP	Feature	Resolved	Normal	[th9800] make radio driver work with tests	02/03/2015 06:49 am
2263	CHIRP	Bug	New	Normal	Newest hungarian translation	01/29/2015 06:05 am
2261	CHIRP	New Model	Feedback	Normal	bf-a58	01/28/2015 02:49 pm
2259	CHIRP	Bug	New	High	Mac Version doesn't have imports for stock configurations	01/27/2015 03:58 pm
2257	CHIRP	New Model	New	Normal	Wouxun KG-UVA1 support	01/25/2015 11:06 pm
2253	CHIRP	New Model	New	Normal	Icom E-7 & Icom T81	01/24/2015 01:01 pm
2247	CHIRP	Bug	Resolved	Normal	[th9800] scan skip/priority not working correctly	02/03/2015 06:50 am
2245	CHIRP	New Model	New	Normal	Yaesu FT-400DR	02/28/2015 08:06 pm
2243	CHIRP	Bug	New	Normal	VX-3R off frequency when programmed with CHIRP	01/23/2015 03:27 pm
2241	CHIRP	New Model	New	Normal	kennwood tk-3160	01/23/2015 11:12 am

2239	CHIRP	Bug	Feedback	High	BF-F9V2+	02/07/2015 06:56 am
2237	CHIRP	Bug	New	High	BAOFENG BF-F9V2+	01/23/2015 06:38 pm
2233	CHIRP	Feature	Feedback	Normal	tone in cross mode	01/24/2015 03:14 pm
2229	CHIRP	Feature	In Progress	Normal	[th9800] add tx inhibit feature per channel	01/19/2015 07:53 pm
2225	CHIRP	Bug	Feedback	Low	Squelch mod related bug. Both BF-E500S and UV5R+Plus ignore new squelch settings yet remember them.	01/19/2015 03:23 pm
2223	CHIRP	Bug	Resolved	Low	Memory tab information not read from .img	01/18/2015 07:14 pm
2221	CHIRP	Bug	Feedback	Normal	TYT UVF1 unable to detect model	01/19/2015 06:23 pm
2219	CHIRP	Bug	Feedback	Normal	Program not saving properly	01/17/2015 01:32 pm
2213	CHIRP	New Model	Feedback	Normal	baofeng bf-a58	01/16/2015 04:04 am
2207	CHIRP	Bug	New	Normal	FT-8800R Upload Programming Issue	01/15/2015 12:23 pm
2203	CHIRP	Bug	New	Normal	Mac OS Yosemite "LSOpenURLsWithRole() failed with error -10810"	01/15/2015 09:28 am
2189	CHIRP	Bug	New	Normal	CAN NOT DOWN LOAD	01/12/2015 03:35 pm
2187	CHIRP	Bug	Resolved	Normal	TYT TH-9800	02/03/2015 06:49 am
2185	CHIRP	Bug	Resolved	Normal	Strangeness with Upload to radio	01/15/2015 03:34 am
2181	CHIRP	Feature	New	Low	at5555 (RP-80 aquario pt-br)	01/11/2015 05:13 am
2169	CHIRP	New Model	New	High	Feidaxin FD-268A / FD-268B	01/06/2015 06:19 pm
2167	CHIRP	Feature	New	High	Modify limits VHF FT-1D	01/06/2015 04:15 pm
2163	CHIRP	New Model	New	High	uv 5r v2 +	01/04/2015 07:29 pm
2161	CHIRP	Bug	Feedback	Normal	Baofeng UV-5RA	01/04/2015 05:04 pm
2157	CHIRP	Feature	New	Normal	New Radio(s) Request	01/03/2015 06:59 pm
2155	CHIRP	Bug	Feedback	Normal	Uv-5r not receiving but will transmitt	01/01/2015 06:00 am
2153	CHIRP	Bug	Resolved	Normal	Baofeng UV-5R TP unsupported firmware ..	01/01/2015 05:15 am
2151	CHIRP	Bug	Feedback	High	tyt th9800	12/31/2014 08:40 am
2149	CHIRP	Feature	New	Normal	[VV-898] Add Settings to Leixen VV-898 Module	12/30/2014 03:59 pm
2147	CHIRP	Bug	Feedback	Normal	Kenwood TH-F6 PL settings rejected	12/30/2014 05:45 pm
2145	CHIRP	Bug	New	Normal	Wouxon KG-UV8D Mode and Power	01/02/2015 12:14 pm
2141	CHIRP	Bug	Resolved	Normal	[TH-D7AG] Max memory name length should be 8	02/01/2015 01:13 pm
2139	CHIRP	Bug	New	High	Chirp not able to download from radio	01/21/2015 03:57 pm
2135	CHIRP	New Model	New	High	Zastone MP600 version (UHF or VHF model)	12/27/2014 04:35 pm
2131	CHIRP	Bug	New	Normal	New Baofeng UV-B5 - Radio did Not Ack ... - OEM soft-Ok	05/15/2015 08:06 pm
2129	CHIRP	New Model	New	Normal	TYT TH-F5	12/26/2014 09:22 am
2127	CHIRP	New Model	New	Normal	Yaesu FT-51R	12/25/2014 09:12 am
2125	CHIRP	Bug	New	Normal	ICOM IC-T70A Upload Error	12/25/2014 07:48 am
2123	CHIRP	Feature	New	Normal	[VV-898] Add Support for TX Inhibited Memories	12/23/2014 07:18 pm

2121	CHIRP	Bug	New	Normal	[VV-898] Changing to "Low" Power Level Does Not Stick	12/23/2014 06:34 pm
2119	CHIRP	Feature	New	Normal	[VV-898] Updates to Prepare for Adding User Settings	12/23/2014 06:15 pm
2115	CHIRP	New Model	Feedback	Normal	software download for Tonfa UV-985 Radio	12/19/2014 06:21 pm
2111	CHIRP	Bug	New	Normal	'hacked' UV-B5 settings not read back	12/17/2014 12:48 am
2109	CHIRP	Bug	Feedback	Normal	Error message programming UV-B5 27 menu version	12/18/2014 12:33 am
2107	CHIRP	New Model	Feedback	High	Add TDXone Q8A VHF/UHF HT radio	01/16/2015 12:19 pm
2105	CHIRP	Bug	Feedback	Urgent	12/10 daily build won't install	12/13/2014 07:19 pm
2101	CHIRP	Bug	Resolved	Normal	[Kenwood TH-D7] Cannot enter '-' as a valid character	02/01/2015 01:13 pm
2097	CHIRP	Bug	Feedback	Immediate	UV-82 Unsupported Firmware US2S25	12/07/2014 06:19 am
2095	CHIRP	New Model	Resolved	Normal	Sainsonic AP510	12/06/2014 03:13 pm
2093	CHIRP	New Model	Resolved	Normal	Pofung GT-1	12/04/2014 04:05 pm
2091	CHIRP	New Model	Resolved	Normal	Add Support for Baofeng BF-F9V2+	04/17/2015 02:36 pm
2089	CHIRP	Feature	New	Normal	Kenwood TM-D710A - support memory channels L0-9, U0-9	11/30/2014 04:57 pm
2087	CHIRP	Bug	New	Normal	Windows: Serial port handle not freed after exception thrown in chirpw	12/11/2014 08:24 pm
2085	CHIRP	Bug	Resolved	Normal	BF-F8HP programming problem - cannot enter Freq > 259.995mhz	11/30/2014 05:51 pm
2083	CHIRP	New Model	New	Normal	Alinco DR-635	02/15/2015 08:32 am
2079	CHIRP	Bug	New	Normal	Uploading on IC-V82 hangs at 50%	11/27/2014 11:07 am
2077	CHIRP	New Model	New	Normal	PRO96 / DTS96	11/26/2014 02:20 am
2075	CHIRP	Bug	Feedback	Normal	error programming	11/25/2014 05:04 am
2071	CHIRP	Bug	New	Normal	[BF-F8HP] Add Support for N5R3401 Firmware	11/24/2014 11:43 am
2067	CHIRP	Bug	Resolved	Normal	GT3 MarkII Not Responding	11/25/2014 09:29 am
2065	CHIRP	Bug	New	Normal	Cannot upload nor download from FT-60	11/28/2014 09:11 am
2063	CHIRP	Bug	New	Normal	HYT	11/20/2014 11:28 am
2061	CHIRP	New Model	New	High	Anytone AT-3318UV Support	11/19/2014 06:51 pm
2059	CHIRP	New Model	New	Normal	Yaesu FT-270R	05/05/2015 10:27 am
2055	CHIRP	Bug	New	High	Yaesu Vx-3R Does not accept Zero as offset	11/14/2014 03:03 pm
2053	CHIRP	Bug	New	High	Crash during upload Yaesu Vx-3R on Mac OS Yosemite	11/26/2014 08:01 am
2051	CHIRP	New Model	New	Normal	new model for programming	11/13/2014 09:02 pm
2049	CHIRP	New Model	New	Urgent	Please do your magic and fully support the Midland HM477 UHF mobile CB unit. It appears to be a clone of the TYT TH9000 but programmed for 477 CBRS	11/12/2014 10:12 pm
2045	CHIRP	Bug	Feedback	High	Baofeng UV-5RA transmits when CHIRP attempts to download clone on OS X Yosemite 10.10	11/13/2014 02:41 am
2041	CHIRP	Bug	New	Normal	Squelch	11/10/2014 10:43 pm
2035	CHIRP	Bug	New	Immediate	bf-f8	11/10/2014 08:01 pm
2033	CHIRP	New Model	New	Normal	KYD IP-620UV	11/09/2014 02:18 pm

2023	CHIRP	New Model	New	Normal	Midland CT-710	11/07/2014 01:14 am
2021	CHIRP	Bug	New	Normal	incorrect read length error for Wouxun KG-UV3D MacOS X 10.10 Yosemite w/NoZAP PL2303 and WXUSB cable	12/06/2014 11:59 am
2019	CHIRP	Bug	Feedback	Normal	I can download but can't upload to any of my FT-60's	12/29/2014 02:31 am
2015	CHIRP	Bug	In Progress	Normal	Wouxun KG-UV8D Settings tab blank	12/02/2014 07:07 am
2013	CHIRP	Feature	New	Normal	RFinder routes query	10/31/2014 01:32 pm
2011	CHIRP	Bug	Resolved	High	RFinder Query fails on positive one digit Longitude	10/31/2014 01:49 pm
2007	CHIRP	Feature	New	Normal	Find duplicate channels function suggestion	10/29/2014 11:01 pm
2003	CHIRP	Bug	New	Normal	Channel Skip Not working on BAOfeng UF-5R	10/29/2014 02:37 pm
2001	CHIRP	Feature	New	Low	shorter marine radio preset channel names	11/02/2014 08:05 am
1999	CHIRP	Bug	New	Low	inaccurate Marine VHF presets for US	11/02/2014 08:06 am
1997	CHIRP	Bug	New	Low	unclear VHF channels in marine preset	05/14/2015 12:12 pm
1993	CHIRP	Bug	Feedback	Normal	Save as	11/01/2014 07:20 am
1987	CHIRP	New Model	New	Normal	programming for Kenwood tk-370G-1 radio	10/22/2014 12:02 am
1975	CHIRP	Bug	In Progress	Normal	Wouxun KG-UV8D - channel name and other data lost when moving frequencies to another channel	10/22/2014 03:26 am
1973	CHIRP	Bug	In Progress	Normal	Wouxun KG-UV8D import from data source	10/22/2014 03:22 am
1969	CHIRP	Bug	Resolved	Normal	Wouxun KG-UV8D - Chirp daily build - can't read from radio	10/16/2014 02:44 am
1965	CHIRP	Bug	New	Normal	Yaesu 8800R Right Side Memory Banks Not Programming	02/05/2015 11:16 am
1963	CHIRP	New Model	New	High	ICOM IC-F34GT	10/14/2014 11:53 am
1961	CHIRP	New Model	New	Normal	ID-51A Anniversary Edition	10/14/2014 12:03 am
1957	CHIRP	Bug	Feedback	Normal	baofeng programming	10/12/2014 11:44 am
1953	CHIRP	New Model	New	High	Icom F10 / F20	10/07/2014 09:47 am
1951	CHIRP	Bug	New	High	Icom F10 / F20	10/07/2014 09:45 am
1947	CHIRP	New Model	New	Normal	Question regarding programming software for Icom IC-P7A	10/05/2014 11:58 am
1943	CHIRP	New Model	New	Normal	Icom IC-V8 as developer trainee	09/28/2014 10:52 am
1941	CHIRP	Bug	New	Normal	Memory name issues on Kenwood TH-D7A(G)	09/27/2014 09:44 am
1939	CHIRP	Bug	Feedback	Normal	FT-90 not reading	10/15/2014 02:20 pm
1937	CHIRP	Bug	New	Normal	DR-06 programming issue	09/25/2014 02:29 pm
1935	CHIRP	Feature	New	Normal	Auto Set Duplex and offset on import	09/25/2014 09:28 am
1933	CHIRP	New Model	Feedback	Normal	FT-8000R Support?	09/26/2014 04:58 pm
1927	CHIRP	Bug	New	Normal	Baofeng GT-3 programming causes dead receive	09/22/2014 02:57 am
1925	CHIRP	Bug	Resolved	Normal	BF-F8HP "Radio Did Not Respond" error message	09/22/2014 06:47 pm
1923	CHIRP	Bug	New	Normal	setting baofeng to tx and rx out of the range	09/21/2014 03:41 pm
1919	CHIRP	Bug	Resolved	Normal	Baofeng GT-3 mark 3	09/22/2014 06:47 pm

1911	CHIRP	Bug	Feedback	High	.img file with matching Firmware still causes CHIRP to crash and radios to not work	09/17/2014 06:57 pm
1907	CHIRP	Feature	Feedback	Normal	Settings tab	09/13/2014 05:19 am
1905	CHIRP	New Model	New	Normal	Wouxun KG-UV920P	09/12/2014 08:56 pm
1903	CHIRP	Bug	Feedback	Normal	Baofeng BF-F8HP lockup	09/13/2014 01:08 pm
1899	CHIRP	Bug	New	Normal	IC-T8A Frequency upload/download error xxx.xx5 MHz	09/10/2014 07:35 am
1897	CHIRP	Bug	Feedback	Normal	I cannot save a duplex / split frequency	09/09/2014 08:50 am
1895	CHIRP	Bug	New	Normal	Non Standard CTCSS Tones	09/06/2014 05:24 pm
1893	CHIRP	Bug	New	Normal	SFE S850UV	09/04/2014 08:40 am
1891	CHIRP	Bug	New	Normal	Unable to copy/paste memories on FT-8800R	12/28/2014 08:44 am
1889	CHIRP	Bug	New	Normal	Crash on attempt to upload	09/02/2014 02:50 am
1887	CHIRP	Bug	Feedback	Normal	Chirp 0.4.0	12/12/2014 08:49 am
1885	CHIRP	Bug	New	Normal	IC80AD upload crashes Mac 10.9.4	09/17/2014 01:48 pm
1883	CHIRP	Bug	Feedback	Normal	BF-F8+ to BF-F8HP programming issue. (be aware I'm new to the radios and process)	09/21/2014 10:21 pm
1879	CHIRP	Bug	New	Normal	Tonfa TF-Q5 transceiver not recognized.	08/30/2014 03:18 pm
1877	CHIRP	Bug	New	Normal	Slow to program Yaesu FT-8800R	08/31/2014 05:32 pm
1875	CHIRP	Bug	Resolved	Normal	Baofeng UV-5RB cant connect	09/01/2014 04:37 am
1869	CHIRP	New Model	Feedback	Normal	Baofeng new Model BF-F9	08/24/2014 06:55 pm
1867	CHIRP	Bug	Feedback	Urgent	baofeng band unlock	08/24/2014 05:33 am
1865	CHIRP	New Model	New	High	Alinco Dj- V5	01/12/2015 10:07 pm
1863	CHIRP	Feature	New	Normal	[KG-UV6]Improve Support for the Powerwerx Wouxun KG-UV6X	08/23/2014 04:00 pm
1861	CHIRP	Bug	Feedback	Normal	Unable to connect to an FT8900R	08/26/2014 03:04 pm
1859	CHIRP	New Model	New	Normal	Wouxun KG-UV2D Supported?	08/23/2014 09:58 am
1857	CHIRP	Bug	Feedback	Normal	Error Message: Radio does not respond	09/09/2014 11:37 am
1855	CHIRP	Bug	Feedback	Normal	Baofeng UV-5R [Error 2] Could not open USB port	08/21/2014 03:49 am
1853	CHIRP	Bug	Resolved	Normal	Baofeng GT-3 MK-2 chanel reading problem	08/20/2014 05:18 pm
1851	CHIRP	Bug	In Progress	Normal	[UV-5R] Prevent selection of incorrect Baofeng radio model when downloading	08/17/2014 03:52 am
1845	CHIRP	New Model	New	Normal	DR-635	11/29/2014 08:31 am
1843	CHIRP	Bug	New	Normal	Alinco dr-135t -Failure to communicate with radio: Radio returned less than 16 bits	08/16/2014 04:59 am
1837	CHIRP	Bug	Feedback	Normal	UVB5 still stransmits with offset of "off"	08/15/2014 04:18 pm
1831	CHIRP	Bug	New	Immediate	Error message when trying to download info from radio using an FTDI chip in a programming cable for Yaesu FT-2800	08/13/2014 08:50 am
1829	CHIRP	New Model	New	High	IC-9100	08/11/2014 02:12 pm
1825	CHIRP	Feature	New	Normal	Error setting memory: Frequency 0.000000 is out of supported range	08/10/2014 10:21 pm
1823	CHIRP	Bug	New	Normal	Split mode Duplex bug -- Input Frequency column suggestion	08/10/2014 09:38 pm
1821	CHIRP	Bug	Feedback	Normal	Can't upload to FT-1802	08/10/2014 07:35 am

1819	CHIRP	New Model	New	Normal	Please add support for Wouxon KG-UV920P	08/09/2014 06:35 pm
1817	CHIRP	Bug	New	Normal	VX-8: Cleanup patch, add DTMF settings	08/09/2014 11:11 am
1813	CHIRP	Bug	New	Normal	Settings Tab Accessibility using the Orca screen reader	08/05/2014 06:04 am
1811	CHIRP	Feature	New	Low	Use dpkg-divert for /usr/share/pyshared/chirp/util.py in Ubuntu daily deb package	08/04/2014 10:42 am
1809	CHIRP	Feature	Resolved	Low	French VHF Marine frequencies	05/01/2015 02:53 pm
1807	CHIRP	Feature	New	Normal	Add settings to VX-8 module	08/03/2014 04:48 pm
1805	CHIRP	Bug	New	Normal	Rename/Delete and Shift memory clears bank membership	08/02/2014 06:15 pm
1803	CHIRP	New Model	New	Normal	Wouxun KG833 programming	08/01/2014 05:39 pm
1799	CHIRP	Bug	Feedback	High	Yaesu VX-6R Upload to Radio Error	08/08/2014 05:59 pm
1797	CHIRP	Bug	New	Normal	Misleading Message "An ERROR has Occurred"	08/02/2014 07:37 am
1795	CHIRP	New Model	New	Normal	Icom IC-F1010	07/28/2014 07:28 am
1793	CHIRP	New Model	New	Normal	Polmar Work	07/27/2014 01:13 am
1791	CHIRP	Bug	Resolved	Normal	Yaesu VX-6 Upload Error	08/09/2014 07:40 pm
1789	CHIRP	Bug	New	Normal	programmation BJ-9900	07/25/2014 11:15 am
1787	CHIRP	Feature	New	Normal	[developer] More informative Diff tabs window title	07/25/2014 07:40 am
1785	CHIRP	Bug	New	Normal	Yaesu FT-8800 - Right side not getting all settings loaded	10/14/2014 11:12 am
1783	CHIRP	New Model	New	Normal	CRT 270M	07/24/2014 02:59 am
1781	CHIRP	New Model	Blocked	Normal	Kenwood TH-K20A	07/24/2014 10:36 am
1779	CHIRP	Feature	New	Normal	[UI] Enable "Hide Unused Fields" by default	07/29/2014 05:39 pm
1777	CHIRP	Feature	Resolved	Normal	Unable to toggle scrambler on and off in BF-888s	07/28/2014 02:31 am
1775	CHIRP	Bug	New	Normal	Puxing 777	07/20/2014 10:15 am
1771	CHIRP	Bug	Feedback	Normal	Linux version not updated - still stuck at 0.1.12	08/22/2014 02:51 pm
1769	CHIRP	Bug	New	Normal	Getting Chirp to Run on a MacBook running OS 10.8.5	08/10/2014 07:52 am
1767	CHIRP	Feature	New	Normal	[developer] Control address format for full-file dump/diff	07/15/2014 11:33 am
1763	CHIRP	Bug	New	Normal	Please create an AppData file for chirp	07/14/2014 02:49 pm
1755	CHIRP	New Model	New	Normal	Yaesu FTM-400de	07/13/2014 03:43 am
1753	CHIRP	Feature	New	Normal	[developer] Add info re: hex dump modes to "Diff Radios" dialog	07/11/2014 05:29 pm
1749	CHIRP	Bug	New	Normal	Anytone at5888uv Short Read	02/15/2015 03:51 am
1747	CHIRP	New Model	New	Normal	Maxon SM-4150M	07/07/2014 08:55 pm
1745	CHIRP	New Model	New	Normal	Alinco DJ-V57T	07/07/2014 08:50 pm
1743	CHIRP	Bug	New	Normal	Getting Chirp to Run on a MacBook running OS 10.5.8	07/07/2014 11:49 am
1737	CHIRP	Bug	New	High	RepeaterBook data loads wrong Offset?	08/09/2014 11:40 am
1735	CHIRP	Bug	New	High	Yaesu VX-8DR - Frequencies programmed with chirp have frequency offset in TX/TR	07/04/2014 06:11 pm
1731	CHIRP	Bug	Feedback	Normal	Application Lock Up	08/10/2014 07:37 am
1729	CHIRP	Bug	New	Normal	Problem with saving of data	07/02/2014 04:02 am

1727	CHIRP	Feature	Feedback	Normal	Clone my Baofeng UV-5R	06/30/2014 02:25 pm
1721	CHIRP	New Model	New	Normal	Yaesu FTM-400 and FTDR1 C4FM radios	06/28/2014 11:33 am
1717	CHIRP	New Model	New	Normal	Yaesu FT-270R	04/04/2015 10:19 am
1715	CHIRP	Bug	Feedback	Normal	Cannot upload to Yaesu FT-897D (US) Mac OS X	08/05/2014 02:49 am
1707	CHIRP	Bug	In Progress	Normal	Baofeng UV-6 Cloning Problem	05/04/2015 03:03 pm
1705	CHIRP	Bug	Feedback	Normal	Mac upload to VX-8 problem	06/28/2014 09:59 am
1703	CHIRP	Bug	Feedback	Urgent	How can i adjust radio type ?	06/19/2014 04:02 pm
1699	CHIRP	Feature	New	Normal	[developer] Add diffs-only mode to file diff utility	06/18/2014 08:34 pm
1697	CHIRP	Feature	New	Normal	[developer] Control fontsize of file browser display	06/18/2014 02:00 pm
1693	CHIRP	Bug	Feedback	Normal	Yaesu VX-170 Fails to Communicate with CHIRP	08/10/2014 07:36 am
1691	CHIRP	Feature	New	High	different pl tones	06/11/2014 02:32 pm
1685	CHIRP	Bug	New	Normal	Problem run program with russian characters in windows account name.	08/10/2014 08:27 am
1683	CHIRP	Bug	New	Normal	Unsupported band limits 0xef for PX-777 submodel 328	06/05/2014 01:16 pm
1681	CHIRP	Feature	New	Normal	[developer] Control fontsize of hex diff/dump display	06/07/2014 09:38 am
1679	CHIRP	New Model	New	Normal	Wouxun KG-699E	06/02/2014 04:20 pm
1677	CHIRP	Bug	Feedback	High	Can't upload to Icom IC-T70A from Mac	08/16/2014 12:25 pm
1667	CHIRP	New Model	In Progress	Normal	Wouxun KG-UV8D	12/02/2014 07:20 am
1665	CHIRP	Bug	New	Normal	Kenwood TM-D700 will only allow freq change, not pl or others	05/29/2014 02:37 pm
1663	CHIRP	Bug	Feedback	Normal	File New not working	06/06/2014 02:19 pm
1661	CHIRP	New Model	New	Normal	Add Support for Wouxun KG-UV5D	05/27/2014 10:41 am
1659	CHIRP	New Model	New	Normal	Puxing PX-888K	01/18/2015 10:50 am
1657	CHIRP	New Model	New	Normal	Puxing UV-973	05/26/2014 07:30 am
1655	CHIRP	Bug	Feedback	High	Cannot upload to Yaesu FT-817ND (US)	02/03/2015 07:20 pm
1653	CHIRP	New Model	New	Normal	Icom IC-T81a	05/24/2014 06:23 am
1651	CHIRP	Feature	New	Normal	[UV-82] Add Additional Settings and Expand Frequency Range [uv5r.py]	05/22/2014 03:43 pm
1649	CHIRP	Bug	Needs Backport	Normal	Unable to communicate with IC-91A	06/03/2014 04:54 am
1647	CHIRP	New Model	New	Normal	Support for ICOM ID-5100A	03/30/2015 07:22 am
1645	CHIRP	New Model	New	Normal	Nanfone NF-569 and alike	05/20/2014 11:38 am
1639	CHIRP	New Model	New	High	AnyTone AT-3318UV-A	05/16/2014 06:13 pm
1637	CHIRP	Bug	New	Normal	[TM-271] missing tuning steps	05/16/2014 11:41 am
1635	CHIRP	New Model	New	Normal	add puxing px-uv973	05/15/2014 10:43 pm
1633	CHIRP	Bug	New	Normal	Kenwood TM-D700 not supported.	05/14/2014 11:59 pm
1631	CHIRP	Bug	New	Normal	Unicode character in path	08/10/2014 09:17 am
1629	CHIRP	Bug	New	Normal	Update requested but no update comes	08/10/2014 07:09 am
1625	CHIRP	New Model	New	Normal	Support for Yaesu FT-50?	05/09/2014 07:33 pm

1623	CHIRP	Bug	Feedback	Normal	Settings tab is blank	05/11/2014 04:30 am
1621	CHIRP	Bug	New	Normal	KG-UV6D	05/08/2014 11:12 am
1619	CHIRP	Bug	New	Normal	FT8800 Banks no programming on RH side	05/07/2014 04:21 pm
1617	CHIRP	Bug	New	Normal	UV-6	08/14/2014 02:19 pm
1615	CHIRP	Bug	New	Normal	Yaesu VX-8DR - Cannot be imported because mode NFM not supported	08/14/2014 01:03 pm
1613	CHIRP	New Model	New	Normal	CS700	05/11/2014 10:30 am
1611	CHIRP	Bug	New	Normal	Kenwood TH-D72A: Programming 2m repeater results in non-functional memory channel	05/08/2014 08:13 am
1609	CHIRP	Bug	New	Normal	Copying from one list to another	05/02/2014 04:47 pm
1605	CHIRP	Bug	Resolved	Immediate	Baofeng 888s	05/02/2014 01:51 am
1603	CHIRP	Bug	New	Normal	clone error, then port access denied	07/31/2014 05:17 pm
1601	CHIRP	New Model	New	Normal	YAESU FTM400DR	04/30/2014 09:07 pm
1599	CHIRP	New Model	New	Normal	Ritron JMX-150	04/30/2014 07:18 pm
1597	CHIRP	Bug	New	High	Unable to program Yawes A-338Plus handheld radio with THT TH-F8PG	11/12/2014 10:07 pm
1593	CHIRP	Bug	New	Normal	No me arranca el programa	04/29/2014 10:29 am
1589	CHIRP	Bug	Feedback	Normal	still unable to run chirp on mac	08/10/2014 07:53 am
1583	CHIRP	Bug	New	Normal	ft60 chirp woes	04/27/2014 12:37 pm
1579	CHIRP	Bug	New	Normal	radio not responding anymore	04/27/2014 07:02 am
1575	CHIRP	New Model	New	Normal	Please Add Support for Zastone ZT-9908 dPMR	04/23/2014 05:55 am
1571	CHIRP	Bug	New	High	Baofeng UV-82L	04/27/2014 05:48 am
1569	CHIRP	Bug	Feedback	Normal	RepeaterBook data will not upload	04/23/2014 02:28 am
1559	CHIRP	Feature	Resolved	Normal	[UV-B5] Update Frequency Ranges	07/31/2014 05:16 pm
1557	CHIRP	Bug	Needs Backport	Normal	[FT-60] The implementation of memory skip is incorrect.	10/03/2014 10:11 am
1555	CHIRP	Feature	New	Low	Copy/paste does not transfer memory "extra" fields	04/11/2014 04:38 pm
1553	CHIRP	Bug	New	Normal	The right clicked editor window don't show memory "extra" fields if the respective line is empty	04/11/2014 03:09 am
1547	CHIRP	Bug	New	Normal	[FT-60] Chirp should check parity on download	02/01/2015 11:37 pm
1541	CHIRP	New Model	New	Normal	Icom ic R10	04/06/2014 08:57 pm
1539	CHIRP	Bug	New	Normal	Error setting memory: Tuning step 100.00 not supported	04/06/2014 01:50 pm
1537	CHIRP	Bug	New	Normal	Missing translation strings	04/06/2014 12:15 pm
1531	CHIRP	Bug	New	Normal	Ubuntu 13.10 coredump at startup	04/04/2014 02:15 pm
1525	CHIRP	New Model	In Progress	Normal	[NC-630A] Add Support for the KYD NC-630A	04/03/2014 03:44 pm
1523	CHIRP	New Model	New	Normal	Wouxun KG-UV3X Pro	01/14/2015 10:19 pm
1515	CHIRP	Feature	Feedback	Normal	Please add "changelog" in chirp-daily repository	03/25/2014 10:00 am
1513	CHIRP	Bug	Feedback	Normal	Re:	03/24/2014 02:46 am
1511	CHIRP	Bug	New	Normal	VX-8R Failure to Communicate with the Radio: Received Incomplete Image from Radio	07/24/2014 12:24 pm

1509	CHIRP	New Model	Feedback	Normal	MAAS AHT-28-V the same device as UV-5R?	04/06/2014 10:33 am
1505	CHIRP	New Model	New	Normal	Vero VR-500	03/19/2014 08:12 am
1503	CHIRP	Bug	Resolved	Normal	[BJ-UV55] step issue	04/13/2014 04:25 am
1499	CHIRP	Bug	In Progress	Normal	PangoWarning: Invalid UTF-8 string passed to pango_layout_set_text()	03/20/2014 10:25 pm
1495	CHIRP	Bug	Feedback	Normal	Can't upload to Yaesu FT-60 from Mac	08/10/2014 07:57 am
1491	CHIRP	Bug	New	Normal	AnyTone AT-5888UV tone squelch programming problem	03/11/2014 02:52 pm
1489	CHIRP	New Model	New	Normal	Wouxun KG-UV950P Quad Band	11/02/2014 07:10 am
1483	CHIRP	Feature	Resolved	Normal	[ft-7900] add settings support	07/31/2014 05:12 pm
1481	CHIRP	New Model	New	Normal	IC-V8000	09/21/2014 12:26 pm
1477	CHIRP	Bug	Resolved	Normal	[vx-3] - daily build with vx3 fix will not upload to radio	03/07/2014 07:49 pm
1475	CHIRP	Bug	New	Normal	Yaesu VX-8 Upload	03/04/2014 09:38 am
1473	CHIRP	Bug	Resolved	Normal	VX-8 failure to communicate	10/23/2014 06:26 pm
1469	CHIRP	New Model	New	Normal	Yaesu FTM-400DR and FTM-400DE	03/17/2014 10:44 pm
1467	CHIRP	New Model	New	Normal	Yaesu FT-8100R	04/19/2014 02:25 pm
1463	CHIRP	Bug	New	Normal	uv-5r bug	02/28/2014 07:47 pm
1461	CHIRP	Bug	Resolved	Normal	[vx-3] upload error with pl2303 cable	02/23/2014 08:14 pm
1459	CHIRP	Bug	New	Normal	ICOM IC-W32A - CP2102 USB to UART - Mac OSX 10.9.1 - Download from radio fine, Upload to radio fails	02/23/2014 06:19 pm
1455	CHIRP	New Model	New	Normal	Puxing PX-A6 (UHF 400-470MHz)	02/23/2014 09:39 am
1453	CHIRP	New Model	New	Normal	Iradio UV-F9	03/03/2014 12:41 pm
1445	CHIRP	Bug	New	Normal	[vx-3] error when importing into empty memories	02/18/2014 10:18 pm
1441	CHIRP	Bug	New	Normal	BF-888S won't enter programming mode - extra character before ACK	05/14/2014 09:20 pm
1439	CHIRP	New Model	New	High	Quansheng TG-K4AT(UV)	02/09/2014 11:45 pm
1437	CHIRP	Bug	New	Normal	tpe exports	02/10/2014 06:27 pm
1433	CHIRP	Bug	Resolved	Normal	MAC OSX 10.9.1 Yaesu VX-7R Upload Fails	03/13/2014 05:51 pm
1431	CHIRP	New Model	New	Normal	Support for Yedro YC-555D	02/05/2014 11:29 pm
1429	CHIRP	Feature	Resolved	Normal	French translation	04/03/2014 02:10 pm
1427	CHIRP	Bug	New	Normal	Baofeng CTCSS setup wont save/load	02/05/2014 04:55 pm
1425	CHIRP	Bug	Resolved	Normal	Error setting memory: Name character `*' not supported.	02/06/2014 05:42 am
1423	CHIRP	New Model	New	Urgent	Bao-hui or Baohui BH-620	02/05/2014 01:24 am
1419	CHIRP	Bug	In Progress	Normal	FT-60R loss of skip feature during upload and download	02/22/2014 06:46 pm
1415	CHIRP	Feature	Feedback	Normal	Store lat/lon and display on map	01/28/2014 04:50 pm
1409	CHIRP	New Model	New	Normal	IC-T81A for loan, perhaps purchase and loan DJ-G29T	01/26/2014 04:55 pm
1397	CHIRP	Bug	Resolved	Normal	FT-60 and FT-8800 Error reading echo (Bad cable?)	07/31/2014 05:27 pm
1391	CHIRP	New Model	Blocked	Normal	Support for IC-910H	01/28/2014 06:22 am

1389	CHIRP	Bug	Feedback	Normal	Anytone AT-5888UV Not Populating PL Encode When Reading Radio	01/23/2014 01:46 pm
1385	CHIRP	New Model	New	Normal	TYT-9000	03/10/2015 06:34 pm
1383	CHIRP	Bug	New	Normal	px-2r can't read digital code	01/23/2014 09:11 am
1379	CHIRP	Bug	New	Normal	UV 82 firmware B82S1	01/17/2014 03:37 am
1373	CHIRP	Bug	New	Normal	Error when downloading from VX-8DR on Mac	01/15/2014 06:53 pm
1369	CHIRP	Feature	Blocked	Low	Android app	02/05/2014 05:26 pm
1367	CHIRP	Feature	Resolved	Normal	Support reading KG-UV Commander generated CSV files	01/10/2014 03:35 pm
1365	CHIRP	Bug	New	Normal	Anytone frequency errors	01/20/2014 10:40 am
1363	CHIRP	New Model	New	Normal	Alinco DJ-G29 & DJ-G7	10/29/2014 10:05 pm
1361	CHIRP	New Model	New	Normal	"New Model" Icom IC-V8	01/08/2014 01:57 pm
1359	CHIRP	Bug	Needs Backport	Normal	Chirp locks up on Radio Reference	01/23/2014 08:48 am
1355	CHIRP	Bug	Feedback	Normal	Chirp dooes not populate the frequencies	01/08/2014 08:35 am
1353	CHIRP	New Model	Resolved	Normal	TYT TH-9800	01/18/2015 02:29 am
1351	CHIRP	New Model	New	Normal	Wouxun KG-UVD5 Support	01/06/2014 07:39 am
1347	CHIRP	Feature	Feedback	Normal	DDE client for MyDDE (Orbitron) - Doppler effect automatic frequency changer	01/05/2014 10:40 am
1345	CHIRP	Bug	New	Normal	icom ic-t70E banks	01/03/2014 04:18 am
1339	CHIRP	New Model	New	Normal	baofeng uv-8d	12/31/2013 04:56 am
1335	CHIRP	Feature	Resolved	Normal	[BJ-UV55] initial settings support	07/31/2014 05:28 pm
1331	CHIRP	New Model	New	Normal	Yaesu VR-5000	12/28/2013 07:56 pm
1329	CHIRP	Bug	New	Normal	TH-UVF1 "Error in setting value: String expects exactly 6 characters"	12/28/2013 08:07 pm
1327	CHIRP	Bug	New	Normal	TH-UVF1 open image detection fail	12/28/2013 08:03 pm
1325	CHIRP	New Model	New	Normal	Ritron RTX-450	04/30/2014 07:22 pm
1321	CHIRP	Bug	New	Normal	Baofeng UV-5S "Unknown response from radio"	12/27/2013 03:05 pm
1315	CHIRP	Feature	New	Normal	[uv-b5] additional settings	12/25/2013 08:23 am
1313	CHIRP	New Model	New	Normal	Alinco DR-620	12/21/2013 07:30 pm
1311	CHIRP	New Model	New	Normal	ALinco DR-635	12/18/2013 07:50 am
1307	CHIRP	Bug	New	Low	Right-click 'insert row above/below' resulting dialog does not automatically dismiss.	12/17/2013 11:49 am
1305	CHIRP	Bug	Feedback	Normal	[UV-B5 / UV-B6] Channel step not editable	03/23/2014 03:14 pm
1303	CHIRP	New Model	New	Normal	FDC FD-850 Plus	12/17/2013 10:55 am
1293	CHIRP	New Model	New	Normal	ALINCO DJ-190T/DJ-191T	12/12/2013 07:38 am
1291	CHIRP	Feature	New	Normal	add basic settings support for Yaesu VX-3	12/07/2013 07:08 pm
1289	CHIRP	Feature	New	Normal	add basic settings support to for Yaesu VX-6	12/07/2013 06:59 pm
1287	CHIRP	New Model	Blocked	Normal	Kenwood TM-D710G	12/04/2014 12:57 pm
1285	CHIRP	New Model	New	Normal	Blackbox plus radios?	12/04/2013 06:25 pm
1281	CHIRP	Bug	Resolved	Normal	Unexpected Response error for new Baofeng UV-B5	12/04/2013 07:24 pm

1277	CHIRP	Feature	New	Low	chirp help menu should have a link to documentation	12/01/2013 01:00 pm
1275	CHIRP	Bug	Needs Backport	Normal	Kenwood TM-G707 RX range is larger than currently supported	11/27/2013 08:42 am
1273	CHIRP	Bug	Needs Backport	Normal	FT-60r not receiving "on frequency"	12/18/2013 09:11 am
1269	CHIRP	Feature	New	Normal	Linux documentation for connection permission-denied	01/26/2014 04:43 pm
1263	CHIRP	Bug	Resolved	Normal	Download from UV-B5 on Linux gives "Unexpected response"	12/04/2013 07:38 pm
1261	CHIRP	Bug	New	High	UV5RA, Nonfunctioning import and export	11/21/2013 10:44 pm
1259	CHIRP	Feature	Resolved	Normal	developer tool for doing byte/bit level compares	11/20/2013 05:41 pm
1253	CHIRP	Bug	Blocked	Normal	ft2600m	11/19/2013 12:37 pm
1247	CHIRP	Bug	Feedback	Normal	Chirp will not start	11/18/2013 04:17 pm
1241	CHIRP	Bug	New	Normal	locales not included in Linux builds	11/27/2013 06:35 am
1237	CHIRP	New Model	New	Normal	Puxing PX-UV973 - dual-band cross-band repeat radio	11/14/2013 07:58 pm
1235	CHIRP	Bug	New	High	Badfeng UV-5rA	11/14/2013 12:20 pm
1233	CHIRP	New Model	New	Normal	Add Yaesu FT-50R	10/29/2014 10:03 pm
1229	CHIRP	Bug	New	Normal	To add Yaesu FT-8100 to the programming ability listing.	01/15/2015 08:27 am
1227	CHIRP	Bug	New	Normal	TYT TH-UV3R :: radio does not upload memories to CHIRP	11/09/2013 03:25 pm
1225	CHIRP	New Model	New	Normal	Baofeng UV-8	10/02/2014 02:49 pm
1223	CHIRP	Bug	New	Normal	vx-2	11/16/2013 03:54 pm
1221	CHIRP	Bug	New	High	Le programme ne veut pas ouvrir	11/07/2013 03:26 pm
1217	CHIRP	Bug	Resolved	Normal	[ft-90] import/export errors	09/29/2014 11:08 am
1205	CHIRP	Bug	New	Immediate	Baofeng UV-82L wrong frequency	11/01/2013 02:45 am
1203	CHIRP	Bug	New	Normal	[VX-3] banks not recognized by radio if banks have not been used before	10/26/2013 07:58 pm
1201	CHIRP	New Model	Resolved	Normal	BJ UV 55	11/16/2013 07:10 pm
1193	CHIRP	Bug	Feedback	Normal	BF-888 Mac problem	04/16/2014 07:07 am
1191	CHIRP	Bug	New	Normal	[UV-B5] Not in Range Issue with Broadcast FM Presets	10/24/2013 01:12 pm
1189	CHIRP	Bug	New	Urgent	Anytone 5888UV Read Error	10/24/2013 05:04 am
1185	CHIRP	New Model	New	Normal	Baojie BJ-9900	10/30/2014 06:49 am
1183	CHIRP	New Model	Resolved	Normal	Yaesu VX-170	04/07/2014 09:46 am
1181	CHIRP	Bug	Resolved	Normal	Error importig Marine VHF channels into Baofang UV-5RE+	10/20/2013 05:12 am
1175	CHIRP	New Model	New	Normal	Quansheng TG-UV2	02/26/2014 02:39 am
1173	CHIRP	Feature	New	Normal	IC-208H - F-1 and F-2 mic buttons not supported	10/15/2013 06:13 pm
1167	CHIRP	Bug	New	Normal	KG-UV3D 220/144 limited settings	10/31/2013 02:35 am
1165	CHIRP	New Model	New	Normal	FTM-350AR	10/13/2013 04:28 am
1163	CHIRP	Feature	Feedback	Normal	Simple instructions for setting rig for communication	10/21/2013 12:21 am
1159	CHIRP	Bug	Needs Backport	Normal	am & nfm modes reversed on yaesu 8900 - confirm bug #883	10/03/2013 08:03 pm
1155	CHIRP	Bug	New	Normal	chirpw crashes on "pyver.split" on OpenSuSE 11.4	09/30/2013 09:03 am

1153	CHIRP	Bug	New	Normal	CHIRP Won't launch to desktop: Win7	09/28/2013 11:41 pm
1151	CHIRP	Feature	Blocked	Normal	"Comment" Field on the channellist	10/29/2013 04:28 pm
1147	CHIRP	Bug	Feedback	High	Upload Error w/ Yaesu VX7R	09/25/2013 06:02 pm
1141	CHIRP	New Model	New	Normal	IC-T2H	09/18/2013 06:21 pm
1137	CHIRP	Bug	Feedback	Normal	Cannot upload to Skip field	09/17/2013 03:10 am
1125	CHIRP	New Model	Feedback	Normal	Support for Intek HR-2040	09/19/2013 02:07 am
1121	CHIRP	New Model	New	Normal	Yaesu 8000R support	09/07/2013 02:02 pm
1117	CHIRP	Bug	Blocked	Normal	FT-8800R Skip	02/19/2015 09:25 am
1113	CHIRP	Bug	New	Urgent	IC-2100H	09/05/2013 05:55 pm
1111	CHIRP	Bug	Resolved	Normal	CHIRP not connecting to Baofeng UV-B5 even with latest daily build	12/04/2013 07:34 pm
1107	CHIRP	New Model	Feedback	Normal	FT1900	03/19/2014 06:51 pm
1103	CHIRP	Bug	New	Normal	unable to write to Yaesu VX5R	08/30/2013 08:07 pm
1099	CHIRP	New Model	New	Normal	Yaesu FT-270R	08/28/2013 02:08 pm
1095	CHIRP	New Model	New	Normal	Kenwood TK-3107 \ SCMY 3117	08/27/2013 04:32 am
1093	CHIRP	New Model	New	Normal	Kenwood TK-690/790/890	08/25/2013 11:59 am
1091	CHIRP	Bug	New	Normal	Issue #1089 I have finally created stock_config files with great dificulty	08/25/2013 01:54 am
1089	CHIRP	Bug	New	Normal	stock_configs file not opening properly in Windows 8	08/26/2013 04:05 pm
1085	CHIRP	Bug	New	Normal	VX3R FM Broadcast Memory Does not Work	08/20/2013 07:59 pm
1081	CHIRP	Bug	New	Normal	wrong repeater offset in Icom ID-51	08/18/2013 04:48 pm
1075	CHIRP	Bug	New	Normal	Chirp don't work with may UV-5RC	08/17/2013 07:50 am
1071	CHIRP	New Model	New	Normal	HYS TC-171	08/29/2013 07:34 pm
1069	CHIRP	Bug	New	Immediate	Channels/Template won't download - No Error Message Baofeng UV-82	08/17/2013 08:13 am

...